



INSTALLATION SOLUTIONS

GB-0100-1.1 REV. 1

## IB-500 INERTIA BLOCK MATERIAL SAFETY LETTER

UNISORB Inertia Block material which is specified as IB-500-B1 and IB-500-S2 is not considered hazardous under normal conditions of use, as defined by OSHA's HAZARD COMMUNICATION STANDARD; CFR TITLE 29,1920.1200(c) (i-iii).

In addition, UNISORB IB-500 Inertia Block material does not produce any unusual combustion gases other than those that would be normal to wool, synthetic organic fibers, or other materials.

A handwritten signature in black ink, appearing to read "Dustin Shinaver". The signature is fluid and cursive, with the first and last names being more prominent.

**Dustin Shinaver**

*Director of Engineering*

4-21-2025